

**EASY MIG**  
FULL SETTING



RISC  
32bit  
MICROCONTROLLER

**EASY MIG**  
FULL SETTING



**Easy to use**  
all adjustments are made in a simple way  
by the combined use of three potentiometers.

**1**

**Select the Process**

**2**

**Adjust the current**

**3**

**If you weld with wire, adjust the arc voltage**

